IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants: John Piechowiak et al.) CONFIRMATION NO. 2684
Appln. No.: 10/730,742	This Request For Certificate Of Correction Of Patent For PTO Mistake was electronically filed on February 20, 2007 using the U.S. Patent and Trademark Office's EFS Web Web
Filed: December 8, 2003	
Title: METHOD, SYSTEM AND APPARATUS FOR OPENING DOORS	
Patent No.: 7,151,351 B2	
Issued: December 19, 2006)
Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450	
ATTENTION: Certificate of Correction Branch	1

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE

Office of Patent Publication

Sir:

In accordance with 37 C.F.R. § 1.322(a), the above-specified patentees, through their attorneys, respectfully request that a Certificate of Correction be issued for the above-referenced patent to correct the following errors.

The exact page and line number where the errors occurred in the application file are:

Please insert the following paragraphs before "Programming Car Remote" Column 8, Line 23

remote's battery is low. Change Car Remote battery as soon as possible.

SAFETY FAULT: A safety fault symbol illuminates when photo eye sensors have been tripped or there is a door jam.

LOCK: Illuminates when the system vacation lock is engaged. --

REMARKS

The above-requested changes result from errors which occurred during printing of the patent on the part of the Patent Office. Attached hereto is Form PTO/SB/44 incorporating the requested changes.

It is believed that issuance of a Certificate of Correction is appropriate without expense to the Patentee, and issuance of such Certificate is respectfully requested.

Please send the Certificate to:

Kenneth H. Samples, Esq. FITCH, EVEN, TABIN & FLANNERY 120 South LaSalle Street, Suite 1600 Chicago, Illinois 60603-3406

Respectfully submitted,

FITCH, EVEN, TABIN & FLANNERY

Date: 2//9/07

Kenneth H. Samples

Registration No. 25,747

120 South LaSalle Street, Suite 1600 Chicago, Illinois 60603 312/577-7000

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _1_ of _1_

PATENT NO.

: 7,151,351 B2

APPLICATION NO.

: 10/730,742

ISSUE DATE

: December 19, 2006

INVENTOR(S)

: John Piechowiak et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Please insert the following paragraphs before "Programming Car Remote" Column 8, Line 23

- - LOW BATTERY: A low battery symbol illuminates when car remote's battery is low.

Change Car Remote battery as soon as possible.

SAFETY FAULT: A safety fault symbol illuminates when photo eye sensors have been tripped or there is a door jam.

LOCK: Illuminates when the system vacation lock is engaged. --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Fitch, Even, Tabin & Flannery 120 South LaSalle Street, Suite 1600 Chicago, Illinois 60603-3406